



SCOTT W. LINDQUIST, MD, MPH, DIRECTOR
345 6TH STREET, SUITE 300
BREMERTON, WA 98337-1866
(360) 337-5235

September 1, 2009

Janet Lunceford
City of Bremerton
345 6th St., Suite 600
Bremerton, WA 98337

RE: SESKO TANKS ASSESSMENT

Dear Janet:

The Kitsap County Health District (Health District) is writing to relay the results of our inspection of the two large tanks on the beach at the north end of Thompson Drive in Bremerton, WA.

Health District staff inspected the tanks this morning. Staff used a photo ionization detector (PID) to check for combustible gases. Three areas on each tank were checked with the PID. These were the pipe openings at the base of each end of the tanks and an open hatch on the top of each tank. No combustible gases were detected. In addition, there was no odor of petroleum products in the area of the tanks.

A visual inspection was conducted for any signs of asbestos. The exterior of the tanks were all metal, with a concrete patch on one of the tanks. The interior of the tanks were checked with a flashlight from the open ports on top of the tanks. No sign of asbestos containing material were seen. The interior appeared to be metal only.

If you have any questions please feel free to contact me at (360) 337-5605.

Sincerely,

A handwritten signature in black ink, appearing to read "Grant A. Holdcroft".

Grant A. Holdcroft, R.S.
Environmental Health Specialist
Solid and Hazardous Waste Program

gah/complaints/sesko tanks

DNR-00007799